



PUR Cleaner

CLEANER FOR PUR-MOUNTING UNG / REMOVES NON-HARDENED PU-FOAM

- ✓ Easy to use
- ✓ Fits on all standard PUR guns
- ✓ Suitable for all PU foams

Insulate & airtight

Technical Info

- Appearance (at 20°C): liquid
- Vapour pressure 20°C \geq 3000 hPa
- Vapour pressure 50°C \geq 8000 hPa
- Relative density 20°C: 0.79
- Water solubility: soluble
- Relative vapour density >1
- Soluble in ethanol, ether, chloroform
- Shelf life: 12 months if kept dry, cool and frost-free

Packing

PUR Cleaner - aerosol 500ml

670801000

Product

Characteristics

- Easy to use.
- Suitable for all PU foams.

Applications

- Cleaning of PU foam guns.
- Removal of uncured PU foam.

Use

- CLEANING OF THE PU GUN
 - Turn the dosing button of the gun completely shut, before screwing PUR Cleaner onto the gun.
 - Screw the can onto it up to the blocking position.
 - Then turn the dosing button completely open and press the lever of the gun completely in so as to remove the foam residues from the gun.
 - Repeat like this until the cleaning agent comes out pure.
 - Once again turn the dosing button completely shut, after which you can screw the PUR Cleaner can from the gun.
 - Clean the ring thoroughly and remove any remaining product from the gun.
 - Always store the gun dry.
- REMOVING UNCURED PU FOAM
 - Install the provided spout on the can.
 - Check whether the surface to be treated is resistant to PUR Cleaner. In case of doubt, first do a test on a spot that is not normally visible.
 - Then apply PUR Cleaner to a cloth and use it to clean the surface.
 - If necessary, repeat this treatment.